



# The Advanced Photon Source RF Systems

## *-- Performance and Upgrades – 2012-2014*

Doug Horan  
Advanced Photon Source  
RF Group  
ASD Seminar  
November 12, 2014


# APS Storage Ring RF Topology

- Waveguide switching system provides twelve modes of operation with different combinations of rf systems
- Routine storage ring operation is 103mA maximum stored current in “top-up” mode
- Requires two klystrons driving storage ring, each operating at ~ 675kW CW
- “Offline” rf stations are in diode, 70kV/5A



# APS Booster RF Topology


- Uses one 1-MW klystron (RF5) operating at 400kW peak, ~ 120kW average power
- Waveguide switching system allows storage ring station RF3 as a back-up to RF5 -- *successfully tested on 7/15/14*



# PAR Accumulator Ring -- RF System Topology


## Fundamental System

- 9.77 MHz
- 4kW CW
- YU-106 triode
- Grounded grid
- Main/backup power amplifiers



## Harmonic System

- 117.3 MHz
- 3kW peak
- 3CX3000A7 triode
- Grounded grid
- Main/backup power amplifiers




# RF System Reliability Statistics

# RF System Downtime – FY2012

## Main RF Downtime Causes:

- 24v linear power supply failed in rf power monitor
- Focus magnet power supply tripped on RF2, and operator error in closing 13.2kV switch

FY 2012 Downtime by System  
Data through Run 2012-2




# RF System Downtime – FY2013

## Main RF Downtime Causes:

- Sector 38 rf cavity vacuum problem
- Intermittent failures of LLRF VXI crate power supply
- Intermittent loss of mod-anode voltage regulation at RF2

FY 2013 Downtime by System  
Data through Run 2013-2



# RF System Downtime – FY2014

## Main RF Downtime


### Causes:

- RF3 crowbar trips
- RF3 klystron sidebands
- Intermittent access door interlock switch
- Vacuum trips at Sector 37 rf cavities
- Intermittent hv cable
- Klystron instabilities and waveguide arcing at RF3

### RF:

- 0.21% downtime
- 544.5 hours Mean Time Between Faults

FY 2014 Downtime by System  
Data through Run 2014-2






# RF System Problems and Hardware Failures


# Intermittent Loss of Mod-Anode Voltage Regulation – *cause of many beam losses*

- 18 years of X-rays from tetrodes damaged teflon wire used to feed heater power to the tetrodes
- Caused intermittent short circuit of heater power
- Damage found in all rf stations
- Wiring was replaced






# Cause of Crowbar Trips – *Failed 50kV Vacuum Switch*

- Two 50kV switches used in series at low end of crowbar test wire
- Switch breaks down in open position, causing intermittent crowbar trips
- No longer available from original manufacturer – found second source





# Sector 36/Cavity #3 “Hot Tuner”

- RF Finger temperature suddenly 25-40°C warmer with hybrid fill pattern – *but normal with 324 singlets*
- Tuner inspection at shutdown shows “plating” on piston.....*gold?*
- Tuner was replaced.....problem didn't return





# Sector 38 RF Cavities – Mysterious Vacuum Problem

- Vacuum pressure in entire sector of cavities started to rise suddenly at the end of post-shutdown beam conditioning -- *highest pressure in cavity 2*
- Pressure continued to rise as the run progressed, and vacuum interlock trip points had to be raised to stay in operation
- Multiple helium leak tests showed no leaks from atmosphere
- Residual gas analyzer indicated traces of chlorine and fluorine
- Tried conditioning during shutdown, but pressure eventually increased to the point that we could not run rf




# Sector 38 RF Cavities – *Mysterious Vacuum Problem*

- Parts were “*shot-gunned*” – Couplers, tuners, and HOM dampers were removed from cavities 1 and 2 – *all parts except for one HOM damper were replaced with new components*
- Vacuum pressure quickly returned to normal levels -- low-mid E-9 Torr
- Cavities were re-conditioned back to operating levels in approximately three days
- Pulled parts were installed in RF Test Stand cavity individually to determine which component was outgassing
- Cavity #2 tuner was the source of gas



# High-Voltage Cable/Socket Failures

- Connector arcing causes crowbar trip and damage to plug and socket



- **Causes:**

- Plug insertion force too low
- Foreign objects in socket
- Insufficient insulating grease
- Intermittent contacts on plugs



# Multiple Problems with RF3

## *Trouble Started With a Klystron Change!*

- **Longest living klystron at APS was retired at RF3:**
  - EEV K3513 s/n 01
  - Retired at 81,209 filament hours
  - 14 years of service with no problems or instabilities
- Replaced with rebuilt spare
- Immediate issues with poor efficiency, crowbar trips, and sideband instabilities
- RF3 was unavailable for an entire run while troubleshooting was in progress
- Multiple causes found:
  - *Significant cathode voltage readback error*
  - *Intermittent HV connectors*
  - *Waveguide arcing*




EEV s/n 01 REMOVED FROM RF3




# Waveguide Arcing at RF3

- Using the EEV klystron, the system would run at  $\approx 700\text{kW}$  for almost an hour, then trip on waveguide arc
- Loud noises coming from the 2<sup>nd</sup>-harmonic damper
- After four or five arc trips to gather data, we shut the system down
- Waveguide was dismantled for inspection during the maintenance shutdown



**2<sup>nd</sup> HARMONIC DAMPER AT RF3**

# Waveguide Arcing at RF3




**ARCING DAMAGE TO HARMONIC DAMPER PROBES**


**Severe damage to harmonic damper pickup probes and terminating loads**



**ALL SIX HARMONIC DAMPER LOADS DESTROYED**



**Cause: Excessive 2<sup>nd</sup> harmonic output from klystron**



# EEV s/n 01 Caused Waveguide Arcing at RF3



- EEV s/n 01 was brought out of retirement and re-installed in RF3 to help troubleshoot system
- Klystron produced excessive 2<sup>nd</sup>-harmonic power.....why?
- Klystron rf cavity tuning nuts were found to be loose on cavities 3 and 4
- EEV s/n 01 retired permanently!
- Replaced with new Thales klystron s/n 089048
  - *Efficiency at 650kW output is ~ 4-5% lower than other Thales klystrons*
  - *Some sideband instabilities, but avoidable with careful adjustment*



EEV s/n 01

# Klystron Sideband Instabilities

- A common problem with Thales TH2089A
- Two types:
  - *Back-streaming electrons* -- Thought to be caused by back-streaming electrons from the collector accelerated towards the cathode by output cavity gap voltage. Sideband frequency is typically  $351.93\text{MHz} \pm$  the difference between resonant frequency of cavity 1 and cavity 2:  $\approx \underline{2.2\text{MHz}}$  →
  - *Cavity multipactor* – Caused by multipactor in the first or second rf cavities. Sideband frequency is typically  $351.93\text{MHz} \pm 1\text{MHz}$  or less →
- Sidebands can exist at fixed frequencies, or drift in frequency randomly
- Can be controlled by careful adjustment of cathode voltage, output match (circulator bias), and rf drive level



# Shorted MOV in Mod-Anode

- The shorted MOV effectively reduced the plate load resistance of one tetrode from 225k $\Omega$  to  $\approx$  22k $\Omega$



- The power dissipated by the tetrode began to heat the 400 gallons of oil in the tank.....until the system tripped on a “mod anode overtemp” fault



# Failed Banana Plug Connection in RF3 Transformer-Rectifier Set


- During routine maintenance, trace chemical analysis of the T-R set oil detected chemical markers for arcing in the oil
- Problem traced to a partially-inserted banana plug used as the bottom connection to a rectifier stack, located under 3,000 gallons of insulating oil
- The plug eventually overheated and began arcing under load



**DAMAGED PLUG AND MATING SOCKET**


# Failure of Re-tuned Philips YK1350 Klystron in RF5

- Retired from CWDD project in 1995
- Re-tuned from 352.21MHz to 351.93MHz in 2009 and tested to 1MW cw in test stand with no problems
- Installed at RF5 in January 2014
- Operated normally for first run of 2014 with no problems
- Coming out of the May 2014 maintenance shutdown, the klystron beam current became unstable
- All attempts to stabilize the gun perveance were futile
- The Philips klystron was removed from RF5 in June 2015 -- the original klystron was re-installed




# Harmonic PAR Driver Amp Failure

- 117.3MHz/500-watt cw commercial amplifier
- Failed during bench testing into load
- Input and output leads were disconnected with dc power applied
- Suspected instability in design
- Not repairable






# Destruction of a Mod-Anode Tetrode Tube Due to a Malfunctioning Crowbar



**CROWBAR FAILED TO FIRE IN RESPONSE TO A HIGH VOLTAGE FAULT**

# T-R Set Resistor Failure

- Found during routine measurement of RF4 capacitor bank
- Measured  $7.5\mu\text{F}$  rather than expected  $8.1\mu\text{F}$
- Found resistor in series with capacitor open on one end
- Failed due to age, temperature, crowbar event stress, oil.....???



# Potential Problem?

## -- *Water in 13.2kVAC and 1400VAC Underground Conduits*

- Conduits run between outdoor transformer pads and rf building
- Cables are almost 20 years old
- Possible failure due to freeze-thaw stress?



# RF System Upgrades and Improvements

# RF System Hardware Upgrades 2012-2014



**REPLACEMENT OF ORIGINAL T-R SET FILTER  
BANK CAPACITORS**




**NEW PLC CONTROL SYSTEM TO REPLACE  
ORIGINAL OBSOLETE CONTROLS**

# RF System Hardware Upgrades 2012-2014



**NEW KLYSTRON DRIVER AMPLIFIERS TO REPLACE  
OBSOLETE ORIGINAL UNITS**





**NEW 352MHz MODULATOR AND  
PHASE SHIFTER LLRF BOARDS**

# RF System Hardware Upgrades

## 2012-2014 -- Harmonic PAR Output Isolator

- 117.3MHz/4kW average rating
- Provides >20dB isolation between amplifiers and cavity
- Amplifiers can be tuned for best efficiency with minimum effect on cavity resonance
- Cavity can be operated off-resonance for physics reasons without stressing amplifiers with reflected power
- Switch to back-up amplifier now causes minimal change in cavity tuning loop operating point




↑  
FULL POWER TEST

←  
ISOLATOR  
INSTALLED

# Conversion to Solid State High Voltage Switch in Linac Modulators

- Presently installed in four out of the six Linac modulator systems
- Replaces expensive consumable thyatron tube
- Provides improved performance, reduced complexity, improved reliability, and long-term operating cost savings






# Replacement of Linac Modulator PFN Capacitors

- Presently installed in four out of the six Linac modulator systems
- Replaces original capacitors that have reached the end of their expected operating lifetime
- Provides improved performance and long-term reliability




# Replacement of Linac Modulator PLC Control Systems

- Project completed at all six Linac modulators
- Replaced obsolete and un-supported cathode ray tube touch screen monitors with LCD touch screens
- Provides improved reliability and long-term serviceability



# Updated Harmonic PAR Cavity Tuner Power Supplies

- Replaced 20 year old analog linear transistor amplifiers



- New amplifiers utilize Class-D switching amplifier technology
- Much greater efficiency, reducing heat load and space requirements in racks
- Provides improved current waveform reproduction, and improved reliability
- Main/standby switching capability to shorten recovery time in the event of an amplifier failure




# Collaboration with CERN – A New Storage Ring Cavity Input Coupler

- Design goal for APS is 200kW cw power handling capability
- Prototype reached 200kW cw in APS RF Test Stand
- Evidence of minor arcing on ceramic noticed after test:




- Analysis underway to determine the cause of the arcing and solve the problem





COUPLER AND WAVEGUIDE TRANSITION  
INSTALLED ON TEST STAND CAVITY

# Solid State RF Power Development at APS – New 9.77MHz/1kW Driver Amplifier for PAR

- Design to replace 20-year old drivers
- Uses one Freescale 1.25kW push-pull LDMOS transistor package



- Broadband transformer matching for simplicity
- Air cooling



## The people who did all this work:

- Roy Agner
- Mike Douell
- Mike Drackley
- Bruce Epperson
- David Jefferson
- Tim Jonasson
- George Kotsiopoulos
- Mark Moser
- William Yoder
- Ali Nassiri
- Tim Berenc
- Dave Bromberek
- Alex Cours
- Eddy Goel
- Art Grelick
- Hengjie Ma
- David Meyer
- Terry Smith
- Gian Trento
- Geoff Waldschmidt

