

Drawing Program error

To fix. Warning drawing program has an error.

1. Creo must be completely empty. Nothing in session.
2. Check out the drawing and part or assembly.
3. Delete the DNT symbol, from the drawing.
4. Delete the NFF-NOTE layer, from the drawing.
5. Run the mapkey RTF.
6. Select Part.txta or Assy.txta.
7. Click on Resume, a bunch of windows open and close.
8. Save and upload and check in the drawing, part or assembly.
9. Continue with the promotion request.

To check the drawing program.

1. Select the Tools tab.
2. Select Drawing Program.
3. Select Edit Program, from the pop up window.
4. There must be 21 lines of program.
5. Done/Return to get out of the program.