

Updates on Laser and Electrical Safety

***Edmund Chang
AOD ESH Coordinator***

***APS Operations Division
Advanced Photon Source
630-252-6714***

change@aps.anl.gov

November 18, 2004

2:55 pm

Building 402 APS Auditorium

Argonne National Laboratory



*A U.S. Department of Energy
Office of Science Laboratory
Operated by The University of Chicago*



Update On Laser Safety: Recent Events

- **24 Laser Restart Visitations: 11-17-04**
- **LCA Supervisor's Meeting: 11-16-04**
- **ANL Laboratory Laser Training 11-3 and 11-4**
- **Office Of Science ES&H Televideo on Laser Safety – ANL and BNL laser accidents**
- **November 19, 2004**
- **ANL Laser Report: TBD**
- **Observations: Improvements On Engineered Controls**

Update: Electrical Safety NFPA 70E

- **Worker Protection Program**
- **Laboratory Directed Criteria: 3 JHQ ?**
- **P6.2 Energized Circuits 50 volts or greater**
- **10 User Yes Responses**
- **P6.5 Energized Conductors 600 volts or greater**
- **2 User Yes Responses**
- **P7.1 Responsibilities with Lockout/Tagout**
- **10 User Yes Responses**
- **19 Unique User Employees Requiring Training**

Update: Electrical Safety

- **Training Dates for NFPA 70E**
- **December 15 and 16, 2004**
- **Laboratory Criteria**
- **If Exposed to 250 volts AC or less with 10K AFI**
- **Safety Glasses**
- **Long Sleeve Cotton Shirt and Pants**
- **NFPA 70E rated gloves**
- **Procedures / Work Permit Reviewed**
- **ASD/QA Representative: Tom Barsz PPE info**